

(107)

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 21, 22, 27, and 28, T. 1 N., R. 6 W.,
W. M., Tillamook County, Oregon.

ORIGINAL

Stone, 24" x 14" x 6"; now 0.9 ft. south of point described in
original field notes as point from which a:

12" Hemlock bears N03W 16 lks; now 18" snag, old face
burnt out but axe marks on top and bottom of burnt
out face exposed.

RESTORED CORNER AND BEARING TREES


Set a 1½" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T1N R6W S21 S22 S28 S27 1951
2311", 2½ ft. in ground. Raised mound of rock around pipe,
from which a:

- 34" Fir stump bears N86W 30.5 ft.; scribed T1N R6W S21 BT 2311.
- 16" Fir snag bears S85E 21.5 ft.; scribed T1N R6W S27 BT 2311.
- 23" Fir snag bears N17E 50.8 ft.; scribed T1N R6W S22 BT 2311.
- 11" Fir snag bears S59W 37.1 ft.; scribed T1N R6W S28 BT 2311.

Placed an Oregon State Board of Forestry metal location poster on
18" Hemlock snag BT and marked it: Sec 21 T1N R6W Sec Cor
10.6 ft. S03E.

Dated December 31, 1951.

This corner was restored by Don D. Davis
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Douglas Stafford Chairman.