

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to sections 6 and 7, T. 2 S., R. 7 W., W.M., Tillamook County, Oregon.

ORIGINAL

Post; now only the point of an old rotted out stake found, from which a:

- 45" Fir bears N48 $\frac{1}{2}$ W 28 lks; now 54" stump; scribe marks R7W faintly visible on burnt face.
- 36" Hemlock bears N53 $\frac{1}{2}$ E (distance not known); now only roots remain N53 $\frac{1}{2}$ E 23'.
- 8" Hemlock bears S69 $\frac{1}{2}$ E 30 lks; now missing.

RESTORED CORNER AND BEARING TREES

Set 1 $\frac{1}{2}$ "x36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R7W R8W S6 S7 S1 CC 1952 2311", 2 $\frac{1}{2}$ ' in ground. Raised mound of stone around pipe, from which a:

- 5' Fir stump bears S11 $\frac{1}{2}$ E 37.0'; scribed T2S R7W S7 2311 BT.
- 6' Cedar stub 10' high bears N81W 55.4'; scribed CC S6 S7 BT.

Placed an Oregon State Board of Forestry metal location poster on 5' Fir stump BT and marked it: Sec 7 T2S R7W Sec Cor 37.0' N11 $\frac{1}{2}$ W.

Dated January 29, 1952.

This corner was restored by
under my direction.

Don D. Davis
Don D. Davis Assistant Forest Engineer



Present and witnessed by

Richard A. Morris
Richard A. Morris Compassman