

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 26 and 27, Township 3 North, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

20" x 20" x 15" stone, now 12" x 6" x 6" stone marked 1/4, out of place, from which a:

10" Hemlock bears S30W 13 lks; now 12" down stub.

16" Hemlock bears N50W 16 lks; now 16" down stub, exposed scribe marks BT.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S27 S26 1952 2311, 2 1/2" in ground. Placed 1/4 stone on north edge of pipe and raised mound of stone around corner pipe, from which a:

42" Fir snag bears N48°30'W 21.1'; scribed 1/4 S27 BT 2311.

42" Fir stump bears S54°30'E 4.9'; scribed 1/4 S26 BT.

Placed an Oregon State Board of Forestry metal location poster on 42" Fir stump BT and marked it: Sec 26 T3N R3W 1/4 Cor 4.9 Ft. N54°30'W.

Dated April 7, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman