

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 15, 16, 21, and 22, Township 1 South,
Range 7 West, W.M., Tillamook County, Oregon

ORIGINAL

Post, now missing, from which a:

- 26" Hemlock bears N15°30'E 63 lks; now 42" down snag,
scribe marks T1S R7W S15 exposed.
- 10" Hemlock bears S42E 86 lks; now missing.
- 6" V. maple bears N65°30'W 41 lks; now missing.
- 6" V. maple bears S18°30'W 60 lks; now missing.

RESTORED CORNER AND BEARING TREES


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T1S R7W S16 S15 S21 S22
1952 2311," 2½" in ground. Raised mound of stone around
pipe, from which a:

- 49" Fir snag bears N33W 9.0°; scribed T1S R7W S16 BT 2311.
- 46" Fir snag bears S22°30'W 32.9°; scribed T1S R7W S21 BT.
- 61" Fir stump bears S26°30'E 35.9°; scribed T1S R7W S22 BT.
- 30" Fir stub bears N45E 21.8°; scribed T1S R7W S15 BT 2311.

Placed an Oregon State Board of Forestry metal location poster
on 49" Fir snag BT and marked it: Sec 16 T1S R7W Sec Cor
9.0 Ft S33E.

Dated April 15, 1952.

This corner was restored by Don D. Davis,
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chairman