

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 22, 23, 26, and 27, Township 3 North, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 58" Hemlock bears N60E 26 lks; now missing.
- 24" Hemlock bears S42E 35 lks; now 30" stump, scribe marks T3N exposed.
- 40" Hemlock bears S51W 15 lks; now 56" snag, exposed parts of scribe marks 3N RSW.
- 36" Hemlock bears N18W 32 lks; now 40" stump, scribe marks T3N RSW S22 exposed.

RESTORED CORNER AND BEARING TREES

As witness corner, 5 feet south of point for corner which falls on south edge of logging road set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY WC T3N R8W S22 S23 S27 S26 5 ft N 1952 2311," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:

- 32" Fir stump bears N67°30'E 76.7°; scribed WC T3N R8W S23 BT 2311.

Placed an Oregon State Board of Forestry metal location poster on original BT now 56" Hemlock snag and marked it: Sec 27 T3N R8W Sec Cor 9.9 Ft. N51E.

Dated April 8, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chairman