

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 21, 22, 27 and 28, Township 1 South, Range 6 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 12" Hemlock bears N17°30'E 42 lks; now 22" stub 10' high, part of scribe mark visible on edge of burnt out face.
  - 7" Yew bears S34°30'E 77 lks; now 10" down snag.
  - 30" Hemlock bears S65°30'W 16 lks; now 34" snag, part of scribe mark visible on edge of burnt out face.
  - 8" Hemlock bears N24°30'W 13 lks; now missing.
- (Distances measured from center of trees)

RESTORED CORNER AND BEARING TREES

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R6W S21 S22 S28 S27 1952 2311," 2½' in ground. Raised mound of stone around corner pipe, from which a:

- 36" Fir stump bears S22W 10.8'; scribed S28 BT.
- 34" Fir snag bears N41W 6.4'; scribed T1S R6W S21 BT RE 2311.
- 53" Fir stump bears S48°30'E 61.4'; scribed T1S R6W S27 BT.
- 53" Fir stump bears N41°30'E 46.3'; scribed T1S R6W S22 BT.

Placed an Oregon State Board of Forestry metal location poster on 34" Fir snag BT and marked it: Sec 21 T1S R6W Sec Cor 6.4 Ft. S41E.

Dated April 24, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chairman