

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to sections 3 and 4, Township 1 South,
Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 12" Hemlock bears S82°30'E 100 lks; now 24" stub 15' high,
parts of scribes visible on both faces.
- 8" Hemlock bears S22°30'W 92 lks; now 20" down snag,
scribe marks T, S, & 4 on fragments alongside.
- 8" Hemlock bears N30W 47 lks; now 14" down stub out of
place, part of scribe mark visible.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T1N R8W S33 S3 S4 T1S CC
1952 2311," 2 1/2' in ground. Raised mound of stone around
corner pipe, from which a:

- 72" Fir stump bears N60W 15.2'; scribed T1N R8W CC S3
S4 BT.
- 5" Fir bears S29°30'W 144.0'; scribed T1S R8W S4 BT.
- 5" Fir bears S64E 116.0'; scribed S3 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster
on 72" Fir stump BT and marked it: Sec 33 T1N R8W CC 3 & 4
Cor 15.2' S60E.

Dated April 30, 1952.

This corner was restored by Don D. Davis
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chairman