

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 1, 6, 7, and 12, T2N R7 and SW, WM., Tillamook County, Oregon.

ORIGINAL

36" Fir, now 36" Fir stump, from which a:

- 7" Hemlock bears N42E 36 lks; now 8" down snag bears N46E, scribe marks N R W S6 exposed.
- 6" Hemlock bears S5E 46 lks, now 7" down snag, scribes T2N R W exposed.
- 6" Hemlock bears S60W 114 lks, now 16" snag, scribes N R8W S12 exposed.
- 5" Hemlock bears N10W 33 lks, now missing.

RESTORED BEARING TREES

As a reference monument

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY RM T2N R8W R7W S1 S6 S7 S12 Cor 4 Ft. 1952 2311," $2\frac{1}{2}$ ' in ground 4 Feet East of corner point. Raised mound of stone around pipe.


- 40" Fir stump bears S61E 6.8' from corner point; scribed T2N R7W S7 BT RE 2311.
- 54" Fir stump bears N17°30'W 58.9' from corner point; scribed T2N R8W S1 BT.
- 50" Fir stump bears N6E 78.8' from corner point; scribed T2N R7W S6 BT.

Placed an Oregon State Board of Forestry metal location poster on 52" Fir stump and marked it: Sec 1 T2N R8W Sec Cor 31.5' S10E.

Dated August 15, 1952

This corner was restored by my direction

Richard Morris, under
Richard A. Morris - Compassman



Present and witnessed by

Robert A. Young
Robert A. Young - Chairman