

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 3, 4, 9, and 10, T2N R7W, WM., Tillamook County, Oregon.

ORIGINAL

Basalt stone 18" x 14" x 10" , now in place marked with 5 notches on South and 3 on East faces, from which a:

- 8" HemLock bears N29E 56 lks; now 9" stub 11" high, 38.5 Ft., face burnt out.
- 40" Fir bears S69E 14 lks, now 51" stump, face unexposed.
- 13" Hemlock bears S55W 12 lks, now destroyed, by fallen tree.
- 15" Hemlock bears N75W 69 lks, now 24" down snag out of place, scribe mark 4 exposed.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T 2N R7W S4 S3 S9 S10 1952 2311," 36" in ground. Placed corner stone on North edge of pipe and raised mound of stone around corner pipe, from which a:

- 52" Fir stub 25' high bears N87W 78.4°; scribed T2N R7W S4 BT.
- 50" Fir stump bears S63W 31.5°; scribed T2N R7W S9 BT RE 2311.
- 48" Fir stump bears N62E 24.0°; scribed T2N R7W S3 BT.

Placed an Oregon State Board of Forestry metal location poster on 52" Fir stub BT 25' high and marked it: Sec 4 T2N R7W Sec Cor 78.4 Ft. S87E.

Dated August 15, 1952.

This corner was restored by Richard Morris, under my direction. Richard Morris Compassman



Present and witnessed by Robert A. Young Chairman