

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter section corner common to Sections 2 and 3, T1S, R8W, WM., Tillamook County, Oregon.

ORIGINAL

Post now missing, from which a:

30" Hemlock bears N17°30'E 23 lks., now 30" stub 10' high, scribes 1/4S BT visible.

14" Hemlock bears N53°30'W 31 lks., now 2 Ft. high stump, BT scribes visible.

RESTORED CORNER AND BEARING TREES

Set 1 1/2"x36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S2 S3 1952 2311," 2Ft. in ground. Raised small mound of stone around pipe from which a:


75" Fir Stump bear N24E 75.4 Ft.; scribed 1/4S BT RE 2311.

63" Fir stump bears North 28.7 Ft.; scribed 1/4S BT.

(Oregon State Board of Forestry yellow corner tag on 75" stump BT.)

Dated August 15, 1952.

This corner was restored by Arnold G. Gibson, under my direction. Arnold G. Gibson, Assistant Engineer



Present and witnessed by Richard Morris - Compassman