

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 3, 4, 9, and 10, Township 3 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 24" Hemlock bears N42°30'E 63 lks; now 32" stub 20" high, both faces exposed and burnt.
- 30" Hemlock bears S27E 61 lks; now missing.
- 8" Hemlock bears S59W 22 lks; now 10" stub 2½" high, scribe marks BT exposed.
- 24" Hemlock bears N9°30'W 29 lks; now 24" down snag, badly burnt.

RESTORED CORNER AND BEARING TREES


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S R7W S4 S3 S9 S10 1952 2311," 2½" in ground, from which a:

- 3" Fir bears N86E 35.5'; scribed S3 BT.
- 3" Fir bears S66°30'W 20.0'; scribed S9 BT.
- 3" Fir bears N84W 14.2'; scribed S4 BT.
- 54" Fir stump bears S70°30'E 139.6'; scribed T3S R7W S10 BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster on 3" Fir BT and marked it: Sec 9 T3S R7W Sec Cor 20.0 Ft. N66°30'E.

Dated June 7, 1952.

This corner was restored by Don D. Davis
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chairman