

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Witness one-quarter corner common to sections 6, and 31,
Township 1 & 2 North, Range 6 West, W.M., Tillamook County,
Oregon.

ORIGINAL

Stone 20" x 12" x 8" in pile of stone, now missing, from which a:
12" Alder bears S42E 37 lks; now missing. *Book 4 P. 39*

RESURVEY (TILLAMOOK COUNTY RECORDS)

18" Alder bears N51°47'E 66.4'; now missing.
30" Hemlock bears East 93.9'; now 36" down snag, scribe
marks 1/4 S exposed.

WITNESSED CORNER POINT

As the point for 1/4 corner falls in Wilson River

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY WC 1/4 S36 S6 9/4 Ft. W 1952
2311," 2 1/2' in ground, 9/4 Ft. east of the corner point.
Raised mound of stone around witness corner pipe, from which
a:

24" Maple bears N05°E 110.2'; scribed X BT.
34" Fir stump bears S26°E 98.0'; scribed X BT RE 2311.

Placed an Oregon State Board of Forestry metal location poster
on 34" Fir stump BT and marked it: Sec 6 T1N R6W WC 1/4
Cor 98 Ft. N26W.

Dated November 18, 1952.

This corner was restored by *Don D. Davis*
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Gerald M. Schwalen, Chainman.