

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 20, 21, 28, and 29, Township 1 South, Range 7 West, W.M., Tillamook County, Oregon

ORIGINAL

Post, now missing, from which a:

- 20" Fir bears S71°30'W 31 lks; now 24" Fir snag, scribe marks S29 exposed.
- 24" Hemlock bears N81°30'W 28 lks; now 30" stub 15' high N88°30'W, scribe marks T1S R7W S2 exposed.
- 14" Hemlock bears S58E 25 lks; now missing.
- 40" Fir bears N57°30'E 44 lks; now 50" stump, scribe marks BT exposed.

RESTORED CORNER AND REWITNESSED CORNER POINT


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S20 S21 S28 S29 1952 2311," 2½' in ground, from which a:

- 66" Fir stump bears N58°30'E 37.6'; scribed T1S R7W S21 BT RE 2311.
- 50" Fir stump bears S81°30'E 31.0'; scribed S28 BT.
- 65" Fir stump bears S46°30'W 34.7'; scribed S29 BT.

Placed an Oregon State Board of Forestry metal location poster on original BT now 24" Fir snag and marked it: S29 T1S R7W Sec Cor 20.5' N71°30'E.

Dated November 19, 1952.

This corner was restored by Don D. Davis
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Gerald M. Schwalen, Chairman.