

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 25, 26, 35, and 36, Township 1 South, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL.

14" x 10" x 8" basalt stone, now missing, from which a:

- 24" Hemlock bears N32W 29 lks; now 40" snag 40' high, scribe marks S R8 S26 exposed.
- 10" Hemlock bears N29E 48 lks; now missing.
- 12" Hemlock bears S67E 35 lks; now missing.
- 6" Hemlock bears S25W 51 lks; now missing.

RESTORED CORNER AND REWITNESSED CORNER POINT


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R8W S26 S25 S35 S36 1952 231L," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:

- 3" Spruce bears N37°30'E 61.1'; scribed S25 BT.
- 60" Fir snag bears N43W 23.0'; scribed T1S R8W S26 BT RE 231L.
- 7" Fir bears S23°30'E 92.1'; scribed T1S R8W S36 BT.
- 5" Spruce bears S29W 78.5'; scribed T1S R8W S35 BT.

Placed an Oregon State Board of Forestry metal location poster on 60" Fir snag BT and marked it: Sec 26 T1S R8W Sec Cor 23.0 Ft. S43°E.

Dated November 20, 1952.

This corner was restored by Don D. Davis
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by R. A. Young, Compassman.

Present and witnessed by G. M. Schwalen, Chainman.