

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter section corner common to Sections 19 and 30, Township 2 South, Range 6 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing from which a:

- 36" Fir bears N17E (N67°E) 55 lks.; now 38" stump, scribes S19 BT visible.
- 20" Hemlock bears S11E (S21°E) 20 lks.; now 24" broken stump, scribes visible, tree down.

RESTORED CORNER AND NEW BEARING TREES

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S19 S30 1953 2311" 30 inches in ground, in mound of stone and from which a:

- 50" Fir stump bears S22°E 32.7 ft.; scribed ¼ S RE 2311 BT.
- 48" Fir stump bears N38°E 43.2 ft.; scribed ¼ S BT.

Metal location poster on 48" bearing tree.

Dated January 20, 1953.

Restored by Arnold G. Gibson, under my direction.
Arnold G. Gibson, Assistant Engineer



Present and witnessed by Robert Young.