

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 1, 2, 11, and 12 T1S R8W,
W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 5" Hem bears N56W 15 lks.; now 6", bottom of blaze left.
- 6" Hem bears N61E 47 lks.; now 24" x 3 Ft. stump, BT scribe.
- 6" Hem bears S24E 44 lks.; missing.
- 8" Hem bears S57W 58 lks.; missing.

COUNTY RESTORATION 1-29-42

Set 1 1/4"x36" pipe, now in place, from which a:

- 30" Hem snag bears S84W 8.4 ft.; scribes T1S R8W 1 2 11 12
BT visible.
- 1/2" dowell in root of burned out 60" Fir stump bears N2 1/2 E
18.1 ft.; now in place.

RESTORED

Set 1 1/2"x36" galvanized iron pipe with 3" bronze cap marked
"Oregon State Board of Forestry T1S R8W S1 S2 S11 S12
1953 2311", 30 inches in ground, and from which a:

- 50" Fir stump bears N40E 120 ft.; scribed T1S R8W
S1 BT.
- 36" Fir snag bears S75W 77 ft.; scribed T1S R8W
S11 RE 2311 BT.

Oregon State Board of Forestry metal location poster on
30" Hem snag S84W.

Also poster on 50" Fir stump on East side log road 18
chains West.

Dated March 11, 1953.

Restored by Arnold G. Gibson under my direction



Present and witnessed by Robert A. Cowan