

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 1, 2, 11 and 12, Township 3 South, Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 6" Hemlock bears N49W 27 lks.; now 8" down, roots in place, scribes T3S R8W S2 visible.
- 14" Hemlock bears N41E 26 lks.; now 20" rotted stub 10 ft. high, face gone.
- 4" Hemlock bears S74E 18 lks.; now 12" snag, scribes 8W S visible.
- 5" Hemlock bears S39W 12 lks.; now missing.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S R8W S1 S2 S11 S12 1953 2311," 33 inches in ground, and from which a:

- 56" Fir stump bears N39W 7.2 ft.; scribed T3S R8W S2 BT.
- 29" Hemlock bears N15E 30.2 ft.; scribed T3S R8W S1 BT RE 2311.
- 96" Fir bears S41E 56.1 ft.; scribed T3S R8W S12 BT.
- 13" Hemlock bears S76°30'W 48.2 ft.; scribed T3S R8W S11 BT.

Oregon State Board of Forestry metal location poster on 56" Fir stump BT.

Also poster on white cedar post 0.5 ft. north of pipe.

Dated October 6, 1953.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Robert Schumacher.
Robert Cowan.