

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

East Section corner common to Sections 13 and 24,
Township 2 North, Range 7 West, W.M., Tillamook County,
Oregon.

ORIGINAL

Stone 16" x 9" x 7", missing, from which a:

- 36" Hemlock bears S68W 20 lks.;
now 38" stump, face burned off.
- 36" Hemlock bears N22W 59 lks.;
now 40" stump, scribes
T2N R7W S13 BT visible.

RESTORATION by Crown Zellerbach corp. (no record)

3/4 x 24" galvanized pipe with 1 1/2" lead cap marked
T2N R6-7W 13 24 19 1953, from which a:

4" x 4" x 40" Fir post scribed S24 on SW,
S13 on NW, and S19 on SE diagonals.

Crown-Zellerbach metal poster on 36"
Hemlock BT S68W.

RESTORED by Oregon State Board of Forestry.

Erected mound of stone around pipe from which a:

42" broken Fir stub bears S38W 75.7 ft.;
scribed T2N R7W S24 BT RE 2311.

Oregon State Board of Forestry metal location poster
on 36" Hemlock BT N22W.

Dated November 10, 1953.

Restored by Richard Morris, under
my direction. Richard Morris, Compassman



Present and witnessed by Carl Vold.

Robert Schumacher.