

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Section 25, T1N, R7W,  
W.M., Tillamook County, Oregon

ORIGINAL

Basalt stone 12"x10"x6", found in place under 30" Fir log with  
 $\frac{1}{4}$ " on West side, from which a:

24" Hemlock bears N47°W 12 lks.; now 28" snag, scribes BT  
remaining.

26" Hemlock bears N21°E 69 lks.; missing, point falls in  
slide area.

*E 1/4 - 25 - 1. N. 7.*

RESTORED


Erected mound of stone around West side of original stone,  
from which a:

60" Fir stump bears S88°W 45.4 ft.; scribed  $\frac{1}{4}$ " S25 BT RE2311.

Set 4"x4"x72" white painted Cedar post 4.5 feet NW of stone.  
Oregon State Board of Forestry metal location poster on original  
24" BT, also poster on 60" Fir stump BT.

Dated October 13, 1955.

Restored by Richard A. Morris under my direction.  
Richard A. Morris, Transitman



Present and witnessed by Forrest Logan  
Robert Sturm  
Lloyd Geraths