

Pages 329 to 332 are dup. of this page and were returned to date.

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 20, 21, 28 and 29, T. 3S, R. 9W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 24" Fir bears N85°E. 23 lks.; now 18" snag, scribes and face rotted and burnt off, now bears N75°E.
- 30" Fir bears S85°E. 16 lks.; now 22" stub 5' high, scribes and face rotted and burnt off.
- 24" Fir bears N18°W. 65 lks.; now missing

RESTORATION by U. G. Jackson, County Surveyor, February 1913 (not recorded). This corner shown as (found) on plat of subdivision of Sec. 29 by Jackson in 1913. (Found 4" x 4" x 30" Fir post scribed 29 on SW, 20 CS on NW, 28 on SE and S21 T3S 9W on NE in place with 1" x 52" galvanized iron pipe wired to E. side, and 28" in ground, from which a 24" Fir stub 8' high bears N11°W. 51.6 ft. with scribes S20 visible on broken off piece)

RESTORED

Var. 21½°

Set 4" x 4" x 72" white painted cedar post 1.5 ft. SE of above pipe from which a:

- 42" Fir bears N50°W. 93.1 ft.; scribed CS T3S R9W S20 BT.
- 22" Fir bears S42°W. 25.4 ft.; scribed CS T3S R9W S29 BT RE 1697.
- 29" Fir bears S87°E 103.3 ft.; scribed CS T3S R9W S28 BT.
- 19" Fir bears N46°E. 75.0 ft.; scribed CS T3S R9W S21 BT.

Oregon State Board of Forestry metal location poster on 29" Fir BT.

Dated March 21, 1956

Restored by Richard Morris under my direction, Richard Morris, Transitman

Present and witnessed by: Lloyd Geraths
Robert Sturm

W. E. Wilson