

340
340

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 4 and 5, T. 2N., R 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing, found 3/4" x 34" pipe out of place) from which a:

16" Hemlock bears S82°E. 17 lks.; now 16" snag, scribes 1/4 S remaining.

18" Hemlock bears N88°W. 9 lks.; roots remaining in place.

RESTORED

Var. 21 1/2°

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S5 S4 1956 RE 2311," 33 inches in ground, with old pipe inside, and from which a:

10" Fir bears S61°E. 15.9 ft.; scribed 1/4 S4 BT RE 2311.

12" Fir bears N4°W. 10.7 ft.; scribed 1/4 S5 BT.

Oregon State Board of Forestry metal location poster on 12" Fir BT. Set 4 x 4 x 60" white painted cedar post 1 ft. NW of pipe

Dated April 4, 1956

Restored by Richard Morris under my direction.
Richard Morris, Transitman



Present and witnessed by Robert Sturm
Lloyd Geraths

BOOK 2