

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Baseline Section corner common to Sections 32 and 33  
T.1N, R.8W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 22" x 10" x 6" (now missing) from which a:

- 14" Hemlock bears North 37 lks.; now missing, point falls in slide area.
- 66" Cedar bears N43°E 20 lks.; now 70" snag, old faces position covered by dirt.

RESTORED by L. W. Amort RE 2311, Jan. 17, 1955.

Bark scribed 7" Alder (now 7" uproot scribes S32 S33 visible) from which a:

- 6" Alder bears N14°W 10.9 ft.; now uprooted and buried by slide.
- 78" Cedar snag bears N34°E 48.4 ft.; now 78" stump, scribes T1N R8W S33 BT RE 2311 visible.

OSBF metal location poster on 90" Cedar snag S42°E 20.5', now uprooted by cat, downhill out of place with poster in tact.

4"x4"x70" white painted Cedar post 4' S; now down out of place.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY BT T1N R8W S32 S33 1957 RS 359," 33 inches in ground, in mound of stone, and from which a:


- 72" Cedar snag bears N88°W 3.4 ft.; scribed T1N R8W S32 BT RS 359.

Oregon State Board of Forestry metal location poster on 72" Cedar snag BT.

Reset above 4"x4"x70" white painted Cedar post 2.0' NW.

Dated May 22, 1957

Restored by *Richard A. Morris* under my direction.  
Richard A. Morris, Transitman



Present and witnessed by Lloyd Geraths  
Robert Sturm

BOOK 2