

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY
(See Official Plat)

One-quarter corner common to Sections 30 and 31, T. 1N,
R. 6W, W.M., Tillamook County, Oregon.

ORIGINAL - (No evidence of original corner found)

REESTABLISHED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY 1/4 S30 S31
1956 RS 359," 30 inches in ground, in mound of stone,
and from which a:

36" Fir bears N47°E 29.1 ft.; scribed 1/4 S30 BT
49" Fir bears S75 1/2°E 58.5 ft.; scribed 1/4 S31 BT RS 359

Set 4"x4"x60" white painted Cedar post 1 ft. SW of pipe.
Oregon State Board of Forestry metal location poster on
49" Fir BT.
Corner is 15 ft. North of dry ravine.

Dated October 4, 1956.

Reestablished by Richard Morris under my direction.
Richard Morris, Transitman

Present and witnessed by Robert Sturm

One-quarter corner common to Section 31 (West side)
T. 1 N, R. 6W, W.M., Tillamook County, Oregon.

ORIGINAL (No evidence of original corner found)

REESTABLISHED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY 1/4 S31 1956 RS 359,"
35 inches in ground, in mound of stone, and from which a:



33" by 15 ft. high Fir stub bears N88°E 34.6 ft.;
scribed 1/4 S31 BT RS 359

Set 4"x4"x60" white painted Cedar post 1.5 ft. NE of pipe.
Oregon State Board of Forestry metal location poster on
16" broken off double top 8" yew stub N51°E 25.8 ft.

Dated October 4, 1956.

Reestablished by

Present and witnessed by Richard Morris
Lloyd Geraths
Robert Sturm



with
Correction
37.37.6