

CHAINS

REESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY
(See Official Plat)

One quarter corner common to Sections 11 and 14, T. 1S, R8W, W.M.
Tillamook County, Oregon.

ORIGINAL (No evidence of original corner found)

REESTABLISHED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S11 S14 1956 RS 359,"
33 inches in ground, in mound of stone, and from which a:

18" Hemlock bears N38°E 63.5 ft.; scribed 1/4 S11 BT
104" Fir stump bears S29°E 18.6 ft.; scribed 1/4 S14 BT RS 359

Set 3"x3"x72" white painted Cedar post 1.5 ft. NE of pipe
Oregon State Board of Forestry metal location poster on 14"
Alder S83°W 38.4'

Also poster on 4"x4"x72" white painted Cedar post 2481 ft.
East on W. edge log road.

Dated October 15, 1956.

Reestablished Arnold G. Gibson
Arnold G. Gibson, Assistant Engineer

Present and witnessed by David Steenson
Elbert Driver
Forrest Logan

ESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY
(See Official Plat)

Center one quarter corner of Section 11, T 1S, R8W W.M.,
Tillamook County, Oregon

ESTABLISHED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 0 1/4 1956 RS 359,"
33 inches in ground, in mound of stone, and from which a:

28" Fir bears N84°W 49.5 ft.; scribed 0 1/4 S11 BT
28" Fir bears S28°W 51.5 ft.; scribed 0 1/4 S11 BT
15" Alder bears E 39.4 ft.; scribed (RS 359)-in bark

Set 4"x4"x72" white painted Cedar post 1ft. NE of pipe
Oregon State Board of Forestry metal location poster on 28"
Fir BT N84°W

Also poster on 4"x4"x72" white painted Cedar post 39.5 ft.
South on East edge park road and on North side Highway.

Dated October 15, 1956.

Established by

Present and witnessed by David Steenson
Elbert Driver and Forrest Logan

