

CHAINS

Correction Report

REESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY
(See Official Plat)

One Quarter corner common to Sections 30 and 31, T1N, R6W, W.M.,
Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED Var. $21\frac{1}{2}^{\circ}$ E

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S30 S31 1956 RS 359,"
32 inches in ground, in mound of stone, and from which a:

36" Fir bears $N55^{\circ}E$ 34.7 ft.; scribed $\frac{1}{4}$ S30 BT.



49" Fir bears $S77\frac{1}{2}^{\circ}E$ 66.8 ft.; scribed $\frac{1}{4}$ S31 BT RS 359.

Oregon State Board of Forestry metal location poster on 49"
Fir BT.

Set 4"x4"x60" white painted Cedar post 1' NW
Corner is 15 ft. North of dry ravine

Dated May 31, 1957.

REESTABLISHED by *Richard Morris* under my direction.
Richard Morris, Transitman



Present and witnessed by Robert Sturm
Craig Chambers