

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 2 and 11, T. 1N., R. 8W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (Missing) from which a:

3" Hemlock bears N. 7° E. 20 lks.; now missing, point falls in slide area.

22" fir bears S. 36° E. 27 lks.; now 22" stump, log downhill with edges of burnt out face visible.

Ridge top course S. 20° E. bears East 69 lks.; now in place.

RESTORED

Var. 21-1/2°

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S2 S11 1957 RS 401," 20 inches in ground, in mound of stone 16" high, and from which a:

34" fir snag bears S. 3° W. 17.3 ft.; scribed 1/4 S11 BT.

36" fir stump bears N. 30° W. 23.8 ft.; scribed 1/4 S2 BT RS401.


Set 4" x 4" x 60" white painted cedar post 2.0' NW, Oregon State Board of Forestry metal location poster on 36" Fir stump BT. Also poster on 24" fir stump 766 ft. E. on S. edge of road.

Dated June 4, 1957

Restored by



*Richard A. Morris*



Present and witnessed by C. Chambers