

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Base Line One Quarter corner common to Section 35 T. 1N., R. 7W., W.M., Tillamook County, Oregon.

ORIGINAL

18" x 8" x 5" Basalt stone (now missing) from which a:

80" Hemlock bears S.46°E. 34 lks.; now 63" fir stump, no face or axe work visible.

32" Hemlock bears N.8°E. 44 lks.; now 33" snag, scribe IS visible, rest burnt out.

RESTORED

Var. 21½° E.

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY BL 1/4 S35 1957 RS401," 35 inches in ground, in mound of stone, and from which a:

68" Fir stump bears N.8°E. 58.1 ft.; scribed 1/4 S35 BT RS401.


Oregon State Board of Forestry metal location poster on original 32" Hemlock snag BT. Set 4" x 4" x 60" white painted cedar post 1.5' S.

Dated June 14, 1957

Restored by



Richard A. Morris



Present and witnessed by Lloyd Geraths
Frank Dimmitt
Ron Fox