

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 5, 6, 7 and 8,
T3N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 14"x12"x6" (missing) found 2'x3' rock outcrop
in place) from which a:

- 48" Fir bears N73°E 25 lks.; now 48" stump, upper face
burnt out, scribes BT visible on lower face.
- 12" Hemlock bears S13°E 49 lks.; now just roots remaining
in place.
- 12" Spruce bears S43°W 47 lks.; now 12" uproot, roots in
place, face and scribes rotted off.
- 16" Hemlock bears N40°W 30 lks.; now missing, point
falls in slide area.

RESTORED

Var. 21½°E

Chiseled an X at corner point in 2'x3' rock outcrop,
from which a:

- 11" Fir bears S25°E 40.7 ft.; scribed T3N R8W S8 BT RS 401
- 9" Fir bears N40°W 25.9 ft.; scribed T3N R8W S6 BT.
- 14" Fir bears S56°W 60.9 ft.; scribed T3N R8W S7 BT.

Oregon State Board of Forestry metal location poster on
14" Fir BT.


Set 4"x4"x60" white painted Cedar post 1.0' SE with mound
of stone around.

Dated September 5, 1957

Restored by



Richard A. Morris



present and witnessed by Robert Sturm
Harold Russell