

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

North One-Sixteenth corner common to Sections 10 and 11, T1N, R10W, W.M., Tillamook County, Oregon.

ESTABLISHED by W. W. Curtiss, C.S., July 30, 1897

96" Spruce bears S66E 29 lks. now 97" snag with two grown over notches, no evidence of face.

36" Hemlock bears N72 $\frac{1}{2}$ W 54 lks. now 38" uproot, roots and root hole in place, edges of old rotted out face and old axe work visible.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY N 1/16 S10 S11 1959 RS401", 33 inches in ground, and from which a:

15" Hemlock bears S81 $\frac{1}{2}$ E 10.1 ft.; scribed N 1/16 S11 BT RS401.

22" Hemlock bears S70 $\frac{1}{2}$ W 30.3 ft.; scribed N 1/16 S10 BT.

Oregon State Board of Forestry metal location poster on 15" Hemlock BT.

Set 4" x 4" x 52" white painted Cedar post 1.4' N 40W of pipe.

Dated December 31, 1959

Restored by



Present and witnessed by R. Cop  
E. Nylund