

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 35 and 36,  
T1S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 16" Hemlock bears N24W 19 lks.; now 26" stump cut off below faces, matching piece down hill with scribe / on upper face & BT on lower.
- 8" Hemlock bears N57E 49 lks.; position falls in cat road; log down hill out of place, scribes BT remaining, upper face burnt out.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S35 S36 1960 RS401", 33 inches in ground, in mound of stone, and from which a:


- 34" Fir stump bears N77E 36.2 ft.; scribed 1/4 S36 BT RS401.
- 28" Fir stump bears N11 1/2 W 15.0 ft.; scribed 1/4 S35 BT.

Oregon State Board of Forestry metal location poster on both new BT's.

Set 4" x 4" x 52" white Cedar post 1.0' N.E. of pipe.

Dated October 17, 1960

Restored by



Present and witnessed by Harold Russell  
George Nylund