

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY
(See official plat)

One Quarter corner common to Sections 35 and 2, T1
and 2N, R10W, W.M., Tillamook County, Oregon.

REESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S35 S2 1961 RS401", 44 inches in ground covered
with dirt, and from which a:

- 11" Spruce bears N80W 39.3 ft.; scribed 1/4 S35 BT RS401.
- 5" Spruce bears S65E 173.0 ft.; scribed 1/4 S2 BT.

Oregon State Board of Forestry metal location poster on 4" x 4" x 52" white
painted Cedar post 41.0 ft. West of corner pipe near edge of pasture.
Also poster on 11" Spruce BT.

* * * * *

Var. 21 1/2 E

One Quarter corner common to Sections 1 and 12, T1N,
R10W, W.M., Tillamook County, Oregon.

REESTABLISHED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S1 S12 1961 RS401", 34 inches in ground, and from
which a:

- 42" Hemlock bears S13E 34.1 ft.; scribed 1/4 S12 BT RS401.
- 11" Hemlock bears N22W 65.3 ft.; scribed 1/4 S1 BT.

Set 4" x 4" x 52" white painted Cedar post 1.0 ft. N.W. of corner pipe.
Oregon State Board of Forestry metal location poster on 11" Hemlock BT.

Dated February 27, 1960

Reestablished by

Present and witnessed by H. Russell
R. Cop
G. Nylund

REGISTERED
OREGON
LAND SURVEYOR



MAY 10, 1957
Richard A. Morris
401