

CHAINS

RE-ESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY  
(See official plat)

One Quarter corner common to Sections 2 and 3, T1N, R10W,  
W.M., Tillamook County, Oregon.

No evidence of original corner found.

RE-ESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE  
BOARD OF FORESTRY 1/4 S2 S3 1960 RS401", 33 inches in ground, and from  
which a:

- 12" Hemlock bears N80W 138.2 ft.; scribed 1/4 S3 BT RS401.
- 7" Hemlock bears S9 1/2 E 177.5 ft.; scribed 1/4 S2 BT.

Set 4" x 4" x 52" white painted Cedar post 1.0 ft. SE of corner pipe.  
Oregon State Board of Forestry metal location poster on 12" Hemlock BT.  
Corner sets in dry ravine, which bears N28W.

\*\*\*\*\*

Section corner common to Sections 33, 34, 3 and 4, T1  
and 2N, R10W, W.M., Tillamook County, Oregon.

No evidence of original corner found.

RE-ESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE  
BOARD OF FORESTRY T2N R10W S33 S34 S4 S3 T1N 1961 RS401", 30 inches in  
ground, and from which a:


- 32" Hemlock bears S78W 7.7 ft.; scribed T1N R10W S4 BT RS401.
- 30" Hemlock bears S15E 2.2 ft.; scribed T1N R10W S3 BT.
- 14" Hemlock bears N11 1/2 W 15.9 ft.; scribed T2N R10W S33 BT.
- 16" Hemlock bears N77E 39.2 ft.; scribed T2N R10W S34 BT.

Set 4" x 4" x 52" white painted Cedar post 1.0 ft. SW of corner pipe.  
Oregon State Board of Forestry metal location poster on 14" Hemlock BT.

Dated February 27, 1961

Re-established by

Present and witnessed by H. Russell  
R. Cop  
E. Nylund



*Richard A. Morris*  
MAY 10. 1957  
Richard A. Morris  
401