

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 25, 26 and 35, T1S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL



Post, missing, from which a:

- 12" Hem. bears S52W 36 lks.; missing.
- 8" Hem. bears N70E 64 lks.; missing.
- 56" Spruce bears S61E 81 lks.; root stub in place.
- 32" Spruce bears N38W 69 lks.; roots & root hole in place.

RESTORATION by Elmer Baker May 19, 1904.

- 60" Spruce bears S83W 42 lks.; now 3' high rotten stub, scribes "W B" remaining.
- 72" Fir bears S51E 24 lks.; now 72" snag, outline of rotted out face with axe marks remaining.
- 36" Fir bears N11E 68 lks.; now 36" uproot, roots in place, scribes R9W visible on uproot.

RESTORED

VAR. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R9W S26 S25 S35 1963 RS401", and from which a: 33" in ground,

- 10" Hem. bears S44 1/2 W 28.8 ft.; scribed T1S R9W S35 BT.
- 17" Fir bears N42W 33.9 ft.; scribed T1S R9W S26 BT RS401.
- E & W Ridge Top bears North 132 ft.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. S.W. of corner pipe. Oregon State Forestry Department metal location poster on 10" Hem. B.T.

Dated August 14, 1964.

Restored by

Present and witnessed by H. Russell



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401