

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 2 and 11 (west end),
T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

4" Maple bears S81°E 87 lks.; now missing.

16" Hem. bears N74½°E 57 lks.; now 60" snag, scribes R9W visible on
partially exposed face.

Corner is in a N and S fence line

RESTORED

Var. 21½E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON
STATE BOARD OF FORESTRY T2S R9W S2 S11 S10 1964 RS 401", 32 inches
in ground, and from which a:

69" Hem. bears S39½°E 68.9 ft.; scribed T2S R9W S11 BT RS 401.

10" Hem. bears N76°E 35.2 ft.; scribed T2S R9W S2 BT.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NE of corner pipe.
Oregon State Forestry Department metal location poster on 10" Hem. BT.

Dated February 2, 1965

Restored by Harold J. Russell under my direction.
Harold J. Russell, Transitman

Present and witnessed by A. Duncan
C. Curl



Richard A. Morris
MAY 10 1967
Richard A. Morris
401