

(7)

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

February 1, 1951

Var. 22° E.

Restoration of the $\frac{1}{4}$ corner to sections 28 & 29, Township 2 North, Range 6 West, W.M., Tillamook County, Oregon.

The point for corner determined by the remains of the original bearing trees:

A fir stump, 45 inches in diam., bears S 20° W, a distance of 38.9 feet (59 lks), part of the face had been exposed and scribe marks $\frac{1}{4}$ visible.

Found no evidence of hemlock BT.

At the point for corner:

Set a $1\frac{1}{2}$ inch iron pipe, 3 feet long, with an Oregon State Board of Forestry bronze cap stamped: $\frac{1}{4}$ S29 S28 1951 199.

from which:

A fir tree, 4 inches in diam., bears N 51° E, a distance of 20.2 feet, scribed: $\frac{1}{4}$ S 28 BT.

Placed a metal location poster on a 40 inch fir snag, marked: Sec 29 T2N R6W $\frac{1}{4}$ Cor 18.6 Ft. N 41° W.

Work done by Don Davis, Transitman; Richard Morris and Donald Newlen, Chainmen; Bill Kleeman and Adolf Berglund, Flagmen; under my direction.



Lyle E. Beyers
Forest Engineer

