

(27)

CHAINS

SURVEY FOR THE OREGON STATE BOARD OF FORESTRY

January 10, 1951

Restoration of the $\frac{1}{4}$ section corner between Sections 21 & 22, Township 2 North, Range 6 West, W.M., Tillamook & Washington Counties, Oregon.

Var. 22° E.

The point for corner determined by the remains of the original bearing trees:

A fir stump, 26 inches in diam., bears N 20° W, a distance of 22.4 feet (34 lks.), scribe marks: B' exposed.

A hemlock snag, 8 inches in diam., bears S 55° E, a distance of 11.2 feet (17 lks). Exposed the scribe mark B.

At the corner point:

Set a $1\frac{1}{2}$ inch iron pipe, 3 feet long, filled with charcoal, with an Oregon State Board of Forestry bronze cap stamped: $\frac{1}{4}$ S21 S22 1951 199.

From which:



A fir snag, 26 inches in diam., bears S 19° W, a distance of 34.5 feet, scribed: $\frac{1}{4}$ S21 199 B'.

A fir stump, 36 inches in diam., bears N 12° E, a distance of 26.5 feet, scribed: $\frac{1}{4}$ S22 199 B'.

Placed a metal location poster on a 36 inch fir stump and marked it: Sec. 22 T2N R7W $\frac{1}{4}$ cor 24.8 ft S 12° W.

Placed a mound of stone $1\frac{1}{2}$ feet high, 3 feet in diameter around the corner.

The above work done by Don Davis, Transitman; Richard Morris and Bill Kleeman, Chainmen; John McWade, Flagman; under my direction.



Lyle E. Beyers
Forest Engineer