

CHAINS

RESTORED CORNER FOR THE OREGON STATE BOARD OF FORESTRY

November 14, 1951

The corner to sections 10, 11, 14, 15, Township 2 South, Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL.

Post (now missing) from which as:

12" Alder bears S53E 37 lks; now missing.

14" Alder bears N8 $\frac{1}{2}$ E 39 lks; now missing.

12" Hemlock bears S45 3/4W 39 lks; now missing.

16" Hemlock bears N84W 113 lks; now a 20" stub uprooted & down (scribe marks BT faintly visable), the stump hole of which bears N84W 113 lks.

RESTORED CORNER & BEARING TREES

The point for corner falls in 15 lk creek on the west edge.

At the point for corner

Set a 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked, "OREGON STATE BOARD OF FORESTRY T2S R7W S10 S11 S15 S14 1951 142" 2 $\frac{1}{2}$ ft. in ground from which as:

10" Alder bears N27 $\frac{3}{4}$ W 44 lks; bark scribed T2S R7W S10 BT 142.

5" Alder bears N08E 42 lks; bark scribed T2S R7W S11 BT 142.

5" Alder bears S58E 105 lks; bark scribed T2S R7W S14 BT 142.

42" Fir stump bears S30W 122 lks; scribed T2S R7W S15 BT 142.


(Distances measured from center of bearing trees).

Nailed a metal location poster on the 42" fir stump BT & marked it: Sec 15 T2S R7W Sec Cor 120 lks N30E.



Restored by

Walter M. Robertson



Walter M. Robertson

Present & Witnessed by

Don Davis
Don Davis Asst. Forest Engineer OSBF

Present & Witnessed by

Richard Morris
Richard Morris Chairman OSBF