

(94)

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to section 1, T. 1 N., R. 7 W., W.M., Tillamook County, Oregon.

ORIGINAL

Stone, 12" x 9" x 6"; now missing, from which a:

24" Fir bears N84W 28 lks; now a 30" stump, scribe marks 1/4 S exposed.

15" Cedar bears N14E 16 lks; now a 26" snag, face bruised and burnt out.

RESTORED CORNER AND BEARING TREES


Set a 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S1 1949 199", 2 1/2 ft. in ground. Raised mound of stone around pipe from which a:

28" Fir stump bears N3W 21.0 ft.; scribed 1/4 S1 199 BT.

Placed an Oregon State Board of Forestry metal location poster on 30" fir stump and marked it: Sec 1 TLN R7W 1/4 Cor 18.5 ft S84E.

Dated June 8, 1951.

This corner was restored by Don D. Davis,
Don D. Davis Assistant Forest Engineer
under my direction.



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Douglas Stafford Chainman