

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 12 and 13, T. 2 S., R. 7 W., W.M.,
Tillamook County, Oregon.

ORIGINAL

Post, now missing from which a:

- 17" Hemlock bears S55W 30 lks; now roots remaining.
- 11" Hemlock bears N12E 59 lks; now down 13" stub with roots
in place, exposed scribe marks BT.

RESTORED CORNER AND BEARING TREES


Set a 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T2S R7W S12 S13 1/4 S 1951
2311" 2 1/2 ft. in ground. Raised mound of stone around pipe
from which a:

- 66" Fir stump bears S27 1/2 W 23.7 ft.; scribed 1/4 S13 2311 BT.
- 30" Fir stub, 12 ft. high, bears N39W 54.6 ft.; scribed
1/4 S12 BT.

Placed a metal location poster on 66" fir stump BT and marked it:
Sec 13 T2S R7W Sec Cor 25.2 ft. N29E.

Dated December 31, 1951.

This corner was restored by Arnold G. Gibson,
Arnold G. Gibson Assistant Engineer
under my direction.



Present and witnessed by Don D. Davis
Don D. Davis Assistant Forest Engineer

Present and witnessed by Richard A. Morris
Richard A. Morris Compassman