

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to section 11 and 14, T. 2 S., R. 7 W., W.M., Tillamook County, Oregon.

ORIGINAL

Post; now missing from which a:

14" Hemlock bears N54E 49 lks; now a 14" stub 3 ft. high, scribe marks BT exposed.

8" Hemlock bears S59E 31 lks; now a down 12" hemlock stub, scribe mark T exposed.

RESTORED CORNER AND BEARING TREES

Set a 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY S11 S14 1/4 S 1951 2311", 2 1/2 ft. in ground. Raised mound of stone around pipe from which a:

40" Fir stub, 8 ft. high, bears S4E, 29.5 ft.; scribed 1/4 S14 2311 BT.


24" Hemlock snag bears N8E 89.5 ft.; scribed 1/4 S11 BT.

Placed an Oregon State Board of Forestry metal location poster on the 40" Fir stub BT and marked it: Sec 14 T2S R7W 1/4 Cor 44 lks N3°30'W.

Pipe is on the North edge of down and partially buried fir log.

Dated December 31, 1951.

This corner was restored by Arnold G. Gibson,  
Arnold G. Gibson Assistant Engineer  
under my direction.



Present and witnessed by Don D. Davis  
Don D. Davis Assistant Forest Engineer