

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 29, 30, 31 and 32, T. 1 S., R. 7 W. W.M., Tillamook County, Oregon.

ORIGINAL

Post; now missing, from which a:

- 12" Hemlock bears S80E 26 lks; now a 20" stub 10' high, exposed scribe marks TLS R7W S.
- 45" Hemlock bears N70E 17 lks; now 5' stub badly decayed.
- 12" Hemlock bears N40W 73 lks; now 18" stub badly decayed.
- 8" Barberry bears S60°30'W 36 lks; now missing.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY TLS R7W S30 S29 S31 S32 1952 2311", 2 1/2' in ground, from which a:

- 46" Fir snag bears S52E 71.5'; scribed TLS R7W S32 BT 2311.
- 46" Fir snag bears N16°30'W 41.8'; scribed TLS R7W S30 2311 BT.
- 40" Fir stub 12' high bears N29E 40.7'; scribed S29 BT.
- 4" Barberry (fire hardened) bears S29W 34.1'; scribed S31.

Placed an Oregon State Board of Forestry metal location poster on 46" Fir snag BT and marked it: Sec 32 TLS R7W Sec Cor 71.5 Ft N52W.

Dated February 28, 1952.

This corner was restored by Don D. Davis,
Don D. Davis Asst. Forest Engineer
under my direction.



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman