

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Quarter corner common to sections 25 and 26, Township 3 North,  
Range 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

17" x 8" x 6" stone, now marked 1/4, out of place, from which  
a:

6" Hemlock bears N60W 41 lks; now 8" stub, down and out  
of place, scribe marks BT exposed.

20" Hemlock bears S80E 52 lks, now 26" stub badly burnt  
and rotted.

RESTORED CORNER AND BEARING TREES

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S25 S26 1952 2311, 2 1/2"  
in ground. Placed 1/4 stone on east edge of pipe, from  
which a:

4" Fir bears S65E 15.1'; scribed 1/4 S25 BT.

24" Fir stub bears N26W 39.7'; scribed 1/4 S26 BT 2311.

Placed an Oregon State Board of Forestry metal location  
poster on 52" Fir stump and marked it: Sec 26 T3N R8W  
1/4 Cor 4.3 ft. S80E.

Dated April 8, 1952.

This corner was restored by  
under my direction.

Don D. Davis  
Don D. Davis Assistant Forest Engineer



Present and witnessed by

Richard A. Morris  
Richard A. Morris Compassman

Present and witnessed by

Robert A. Young  
Robert A. Young Chairman