

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Township corner common to sections 1, 6, 31, and 36, Township 2 and 3 North, Range 7 and 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 20" Hemlock bears N70E 31 lks; now 30" stub 15' high, T3N R7W S31 BT exposed.
- 20" Hemlock bears S42E 62 lks; now 24" snag, parts of scribing visible on badly decayed face.
- 20" Hemlock bears S40W 41 lks; now 32" tree leaning east, some scribing visible, did not expose.
- 24" Hemlock bears N22W 11 lks; now 32" down snag out of place, scribe marks T2N R8W S36 exposed. (Original calls for scribing to be T3N R8W S36 BT.)

RESTORED CORNER AND BEARING TREES

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R8W R7W S36 S31 S1 S6 T2N 1952 2311," 2½' in ground, from which a:

- 7" Hemlock bears S39E 33.9'; scribed T2N R7W S6 BT.
- 36" Hemlock bears N70W 62.8'; scribed T3N R8W S36 BT RE 2311.
- 66" Fir stump bears N65E 3.5'; scribed T3N R7W S31 BT.

Placed an Oregon State Board of Forestry metal Location poster on 7" Hemlock BT and marked it: Sec 6 T2N R7W Twp Cor 33.9 Ft. N39W.

Dated April 23, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chairman