

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 25, 30, 31, and 36, Township 3 North, Ranges 7 & 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

24" x 18" x 6" basalt stone, now 16" x 12" x 6" stone marked with five notches on north face, from which a:

- 16" Hemlock bears N20E 41 lks; now 18" root stub.
- 10" Hemlock bears S44E 32 lks; now missing.
- 14" Hemlock bears S77W 37 lks; now 16" root stub.
- 15" Hemlock bears N41W 25 lks; now missing.

RESTORED CORNER AND BEARING TREES


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R8W R7W S25 S30 S36 S31 1952 2311," 2½' in ground. Placed corner stone on north side of pipe and raised mound of stone around corner pipe, from which a:

- 60" Fir stump bears S89E 30.6'; scribed T3N R7W S31 BT.
- 50" Fir stump bears N06E 15.6'; scribed T3N R7W S30 BT.
- 36" Fir stub bears N80W 22.5'; scribed T3N R8W S25 BT 2311.
- 36" Fir stub bears S08W 15.5'; scribed T3N R8W S36 BT.

Placed an Oregon State Board of Forestry metal location poster on 60" Fir snag BT and marked it: Sec 31 T3N R7W Sec Cor 30.6 Ft. N89W.

Dated April 9, 1952.

This corner was restored by Don D. Davis under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chainman