

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 3, 4, 33, and 34, Townships 1 & 2 South,
Range 7 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 6" Hemlock bears S55W 16 lks; now missing.
- 6" Hemlock bears S17E 31 lks; now missing.
- 14" Hemlock bears N45°30'E 16 lks; now missing.
- 20" Hemlock bears N27°30'W 31 lks; now 30" stub, 25' high,
scribe marks T1S R7W S exposed.

RESTORED CORNER AND BEARING TREES


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T1S R7W S33 S34 S4 S3 1952
2311," 2½' in ground, from which a:

- 54" Fir snag bears S44W 52.0'; scribed T2S R7W S4 BT.
- 61" Fir snag bears S40E 75.1'; scribed T2S R7W S3 BT.
- 41" Fir snag bears N29°30'E 40.8'; scribed T1S R7W S34 BT
2311.
- 69" Fir stub bears N54W 75.2'; scribed T1S R7W S33 BT.

Placed an Oregon State Board of Forestry metal location poster
on 54" Fir snag BT and marked it: Sec 4 T2S R7W Sec Cor
N44E 52.0 Ft.

Dated April 14, 1952.

This corner was restored by Don D. Davis
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chainman