

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter corner common to sections 20 and 21, T1N R6W,
WM., Tillamook County, Oregon.

ORIGINAL

Stone 15" x 12" x 8", now marked 1/4 on West face.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S20 S21 1952 2311,"
2 1/2" in ground and placed 1/4 stone on East edge of pipe.
Raised mound of stone around corner pipe, from which a:

26" Fir stump bears N60W 47.3°; scribed 1/4 S20 BT.
55" Fir stump bears N34E 17.7°; scribed 1/4 S21 BT
RE 2311.

Placed an Oregon State Board of Forestry metal location poster
on 26" Fir stump BT and marked it: Sec 20 T1N R6W 1/4 Cor
47.3 Ft. S60E.

Dated August 15, 1952.

This corner was restored by Don D. Davis, under
my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chairman