

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 32 and 33 on the South Township line of T2S R7W, WM., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 15" Hemlock bears N55E 15 lks; now 15" stub 6' high badly decayed and burnt.
- 40" Fir bears S58W 50 lks, now 48" stump, scribe marks T2S R7W S5 exposed (The original call of the field notes is T3S)
- 5" Hemlock bears S34°30'E 20 lks, now missing.
- 3" V. Maple bears N56W 16 lks, now missing.

RESTORED CORNER AND BEARING TREES


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2S R7W S32 S33 T3S R7W S4 1952 231L," 2 1/2' in ground. Raised mound of stone around corner pipe, from which a:

- 42" Fir snag bears N02E 19.6'; scribed T2S R7W S33 BT.
- 42" Fir stub 20' high bears N73W 42.9'; scribed T2S R7W S32 BT RE 231L.

Placed an Oregon State Board of Forestry metal location poster on 60" Fir stump and marked it: Sec 4 T3S R7W Sec Cor 32 and 33 37.0 Ft. N66W.

Dated August 15, 1952.

This corner was restored by Don D. Davis, under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris Richard A. Morris Compassman

Present and witnessed by Robert A. Young Robert A. Young Chairman