

CHAINS

RESTORED FOR OREGON STATE BOARD OF FORESTRY

Corner common to sections 2, 3, 34, and 35, Townships 1 & 2 South, Range 7 West, W.M., Tillamook County, Oregon

ORIGINAL

Post, now missing, from which a:

- 24" Hemlock bears N63W 60 lks; now 36" down snag, face burnt out.
- 24" Hemlock bears S37°30'W 68 lks; now 30" snag, scribe mark T exposed did not attempt to expose rest of face.
- 22" Hemlock bears S32E 68 lks; now 30" stub 20' high S28E 85.0°, scribe marks T1S R7W S2 BT exposed.
- 3" V. Maple bears N55E 60 lks; now missing.

RESTORED CORNER AND BEARING TREES

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S34 S35 S34 S 35 S3 S2 T2S 1952 2311," 2½" in ground. Raised mound of stone around corner pipe, from which a:

- 12" Cedar bears N81W 92.5'; scribed T1S R7W S34 BT RE 2311.
- 72" Fir, bears N30E 47.1'; scribed T1S R7W S35 BT. snag

Placed an Oregon State Board of Forestry metal location poster on 72" Fir snag BT and marked it: Sec. 35 T1S R7W Sec Cor 47.1 Ft. S30W.

Dated May 6, 1952.

This corner was restored by Don D. Davis,
under my direction. Don D. Davis Assistant Forest Engineer



Present and witnessed by Richard A. Morris
Richard A. Morris Compassman

Present and witnessed by Robert A. Young
Robert A. Young Chainman