

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to sections 19 and 30, Township 2 North,  
Range 6 West, W.M., Tillamook County, Oregon.

ORIGINAL

30" Fir, now 36" snag, scribe mark C exposed on E face, from  
which a:

10" Hemlock bears S75E 13 lks; now 10" root stub.

24" Fir bears N34E 22 lks; now 30" stub broken off at  
butt, scribe marks T2N R6W S19 B exposed on broken  
trunk.

RESTORED BEARING TREES

As a reference monument

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY RM T2N T2N S24 S19 S30  
CC R7W R6W 5 Ft. W 1952 2311," 2 1/2" in ground east 5.0'  
from corner. Raised mound of stone around pipe.

25" Hemlock bears N24E 25.0' from corner; scribed T2N  
R6W S19 BT RE 2311.

19" Hemlock bears S88E 45.0' from corner; scribed T2N  
R6W S30 RE 2311 BT.

Placed an Oregon State Board of Forestry metal location poster  
on NE side of CC tree, now 36" snag, and marked it: Sec 19  
T2N R6W CC 19/30 this snag.

Dated June 7, 1952.

This corner was restored by  
under my direction.

*Don D. Davis*  
Don D. Davis Assistant Forest Engineer



Present and witnessed by

*Richard A. Morris*  
Richard A. Morris Compassman

Present and witnessed by

*Robert A. Young*  
Robert A. Young Chairman