

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to sections 25, 30, 31, and 36, Township 2 North, Range 7 West and 8 West, W.M., Tillamook County, Oregon.

ORIGINAL

17"x 12" x 5" basalt stone, now missing, from which a:

20" Hemlock bears N62E 60 lks; now 26" stub, exposed parts of scribe marks along edge of face.

30" Hemlock bears S74°30'E 58 lks; now 42" snag, scribe marks T2N R8W S31 exposed. (Original notes call for scribe marks R7W.)

36" Hemlock bears S84°30'W 19 lks; now 36" stub 3' high.

18" Hemlock bears N61°15'W 22 lks; now missing.

RESTORED CORNER AND BEARING TREES

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R8W R7W S25 S30 S36 S31 1952 2311," 2½' in ground. Raised mound of stone around corner pipe, from which a:

60" Fir stump bears N65W 68.4'; scribed T2N R8W S25 BT.

48" Fir stump bears N70E 66.6'; scribed T2N R7W S30 BT RE 2311.

54" Fir stump bears S70W 64.2'; scribed T2N R8W S36 BT.

52" Fir stump bears S41E 41.5'; scribed T2N R7W S31 BT.

Placed an Oregon State Board of Forestry metal location poster on original BT, now 42" Hemlock snag and marked it: Sec 31 T2N R7W Sec Cor 38.3' N76W.

Dated June 7, 1952.

This corner was restored by  
under my direction.

Don D. Davis  
Don D. Davis Assistant Forest Engineer



Present and witnessed by

Richard A. Morris  
Richard A. Morris Compassman

Present and witnessed by

Robert A. Young  
Robert A. Young Chairman